

# Oil Field Environmental Incident Summary

**Incident:** 20160606135335

**Date/Time of Notice:** 06/06/2016 13:53

**Responsible Party:** PETRO HARVESTER OPERATING COMPANY, LLC

**Well Operator:** PETRO HARVESTER OPERATING COMPANY, LLC

**Well Name:** SCHULTZ 1 SWDW

**Field Name:** FLAXTON

**Well File #:** 10406

**Date Incident:** 6/5/2016

**Time Incident:** 13:30

**Facility ID Number:**

**County:** BURKE

**Twp:** 163

**Rng:** 91

**Sec:** 14

**Qtr:** SW NW

**Location Description:**

**Submitted By:** Gary Watson

**Received By:**

**Contact Person:** Mark Bonnie  
5851 LEGACY CIRCLE  
SUITE 500  
PLANO, TX 75024

**General Land Use:** Cultivated

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 7000 Feet

**Distance Nearest Water Well:** 7000 Feet

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	50	Barrels	50	Barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No explosive risk or immediate health hazard.

**Areal Extent:**

Released fluids were contained within the diked containment area.

**Potential Environmental Impacts:**

No impact to surface water or groundwater or cultivated soils. All released fluids were contained within the diked containment area.

**Action Taken or Planned:**

NDIC Field Inspector Jim Potts was notified telephonically. The diked area initially contained approximately 120 bbls of rainwater from the recent storms that had not yet been vacuumed out. An estimated 50 bbls of produced water leaked from the storage tanks in the 1 hour and 15 min that transpired between the unloading of water trucks. The released fluids and the rainwater will be vacuumed up and pumped in the Schultz 1 SWDW well. The affected well site soil within the dike containment area will be scraped up, collected and hauled to an approved disposal facility. The fiberglass suction line will be replaced and elevated above ground level to prevent future abrasion.

**Wastes Disposal Location:** An approved waste disposal facility.

**Agencies Involved:****Updates**

---

**Date:** 6/6/2016      **Status:** Reviewed - Assigned to Other Agency      **Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report the release was contained to the well pad. NDIC takes oversight.